

**German Intensity Standard
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong

Assessment Area 1

| SMRC RRRC - Field Based Ambient Odour Intensity Assessments | | |
|--|-------------|----------------|
| APRIL 2018 | | |
| | Date | APR |
| | Wind | Light Easterly |
| Street Location | I.D. | Average |
| Cnr. Dundee Street & Beasley Road | 1 | 0 |
| Beasley Road (middle) | 2 | 0 |
| Cnr. Beasley Road & Hollingsworth Way | 3 | 0 |
| Hollingsworth Way (middle) | 4 | 0 |
| Cnr. Hollingsworth Way & Roe Hwy Footpath | 5 | 0 |
| Roe Highway Footpath (middle) | 6 | 0 |
| Cnr. Roe Hwy & Dundee Street | 7 | 0 |
| Dundee Street (middle) | 8 | 0 |
| Cluelow Rise (cul-de-sac) | 9 | 0 |
| Harwood Rise (on elbow) | 10 | 0 |
| Capill Corner (cul-de-sac) | 11 | 0 |
| Noreat Place | 12 | 0 |

Assessment Area 2

| | | |
|---------------------------------------|----|---|
| Blaise Court | 1 | 0 |
| Hollingsworth Way (middle) | 2 | 0 |
| Cnr. Beasley Road & Hollingsworth Way | 3 | 0 |
| Cnr. Beasley & Timbrell | 4 | 0 |
| Timbrell Way | 5 | 0 |
| Timbrell Way | 6 | 0 |
| Cnr. Timbrell & McGuinness | 7 | 0 |
| Cnr. McGuinness & Beasley | 8 | 0 |
| Cnr. Beasley & Merrifield | 9 | 0 |
| Cnr. Merrifield & Roe Hwy | 10 | 0 |
| Sellen Court | 11 | 0 |
| Cnr. Orrock & Sellen Court | 12 | 0 |