



SMRC RRRC - Field Based Ambient Odour Intensity Assessments

May 2018

**German Intensity Standard
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong
- < less than

		Date	MAY
		Wind	Light SE
Street Location		I.D.	Average
Assessment Area 3	Cnr. Merrifield & Roe Hwy	1	<1
	Merrifield (middle)	2	<1
	Cnr. Beasley & Merrifield	3	0
	Beasley	4	0
	Cnr. Beasley & Merrifield	5	0
	Merrifield (middle)	6	0
	Cnr. Merrifield & Roe Hwy	7	0
	Merrifield (middle)	8	<1
	Stenton Corner	9	<1
	Bosworth Place	10	0

Assessment Area 4	Cnr. Merrifield & Roe Hwy	1	<1
	Cnr. Beasley & Merrifield	2	0
	Cnr. South Street & Darian Drive	3	0
	Cnr. Darian Drive & Trident Terrace	4	0
	Trident Terrace (middle)	5	0
	Cnr. Trident Terrace & Plover Drive	6	0
	Cnr. Arlington & Vahland	7	0
	Arlington Drive Elbow	8	0
	Cnr. Vahland & South Street	9	0