



**German Intensity Standard
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong
- < less than

SMRC RRRC - Field Based Ambient Odour Intensity Assessments

November 2016

Street Location	Date	NOV
	Wind	ESE
Street Location	I.D.	Average
Cnr. Dundee Street & Beasley Road	1	0
Beasley Road (middle)	2	0
Cnr. Beasley Road & Hollingsworth Way	3	0
Hollingsworth Way (middle)	4	0
Cnr. Hollingsworth Way & Roe Hwy Footpath	5	0
Roe Highway Footpath (middle)	6	0
Cnr. Roe Hwy & Dundee Street	7	0
Dundee Street (middle)	8	0
Cluelow Rise (cul-de-sac)	9	0
Harwood Rise (on elbow)	10	0
Capill Corner (cul-de-sac)	11	0
Noreat Place	12	0

Assessment Area 1

Blaise Court	1	0
Hollingsworth Way (middle)	2	0
Cnr. Beasley Road & Hollingsworth Way	3	<1
Cnr. Beasley & Timbrell	4	0
Timbrell Way	5	0
Timbrell Way	6	0
Cnr. Timbrell & McGuinness	7	0
Cnr. McGuinness & Beasley	8	0
Cnr. Beasley & Merrifield	9	<1
Cnr. Merrifield & Roe Hwy	10	0
Sellen Court	11	0
Cnr. Orrock & Sellen Court	12	0

Assessment Area 2

Cnr. Merrifield & Roe Hwy	1	0
Merrifield (middle)	2	0
Cnr. Beasley & Merrifield	3	0
Beasley	4	0
Cnr. Beasley & Merrifield	5	0
Merrifield (middle)	6	0
Cnr. Merrifield & Roe Hwy	7	0
Merrifield (middle)	8	0
Stenton Corner	9	0
Bosworth Place	10	0

Assessment Area 3

Cnr. Merrifield & Roe Hwy	1	0
Cnr. Beasley & Merrifield	2	0
Cnr. South Street & Darian Drive	3	0
Cnr. Darian Drive & Trident Terrace	4	0
Trident Terrace (middle)	5	0
Cnr. Trident Terrace & Plover Drive	6	0
Cnr. Arlington & Vahland	7	0
Arlington Drive Elbow	8	0
Cnr. Vahland & South Street	9	0

Assessment Area 4